

Location: IBM Micro Chip Plant entrance and commercial parking lot in Poughkeepsie, New York.

Date: March 25, 2004

Conditions: Left over sand from repeated sand/salt mix applications. Several clean-ups must now take place to put this area back in shape.

- 1. The sand needs to be cleaned up in the roadway.**
- 2. Sand needs to be removed from damaged grass areas, which border the curb line. Grass damage needs to be repaired.**
- 3. Notice sand as it is washed into the storm drain. The storm drain will need to be vacuumed out in time as the sand and debris will clog the drain.**
- 4. Notice additional grass damage from sand/salt use.**
- 5. The grass area along the parking lot curb is undamaged because this contractor used Magic Salt and did not have the grass kill that the sand/salt has.**