

Location: Condominium Complex. Ashland, Massachusetts.

Date: January 10, 2003 8:00 AM

Conditions: Light dusting of snow has fallen. Surface temperature 9° F

- 1) Contractor uses Magic Salt and did not have to spread any material for De-Icing. The contractor had spread Magic Salt four days prior to a storm. The residual Magic Salt, now on the pavement, reacted with the “dusting of snow”, which melted on contact.**
- 2) The end result – the contractor did his job by providing a safe environment. The possibility of a slip and fall was greatly reduced and the contractor did not even show up. The contractor saved labor, time, and material, and has no sand to clean up in the spring.**